TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 526)

Set post in edge of bottom, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on W face; from which
A Cedar, 12" dia., bears S.17°E., 30 lks., mkd: ¼ S BT
A Chittem, 6" dia., bears N.88½°W., 16 lks., mkd: ¼ S BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12935)

Point for the ¼ sec. cor. of secs. 28 & 29, determined from the one remaining orig. BT:
A Cedar, 22" dia., bears S.17°E., 30 lks., mkd. with an old blaze on NW face.
At the corner point
Set an iron post, 3' long, 1" dia., 27" in the ground, with brass cap mkd:

¼
S 29|S 28
1952

from which
A Cedar, 33" dia., bears N.64°W., 51 lks., mkd: ¼ S29 BT.
A Cedar, 15" dia., bears S.61½°E., 60 lks., mkd: ¼ S28 BT.

William Eimstad - For: International Paper Co. - April 1980 - M 84-77

Corner lost to mud & boulder slide. Corner proportioned by broken boundary method:
Set - 5/8" x 20" re-bar in drill hole in boulder.
4-d spike in lead in drill hole N.34°W., 7.15 ft.
8" Fir, N.67°E., 21.1 ft. "W ¼ S28 BT"

Ronald L Rice - For: Oxbow Timber 1 LLC - Oct. 2015 - M170-25

Found - ⅝" rebar in ground (record in drill hole in bolder) with the following accessories:
4D spike in lead drill hole in boulder bears N.34°W., 7.15'.
17" D.Fir bears N.67°E., 21.1', healed face.
New BTs- 13" Alder bears S.12°W., 9.6', bark scribed ¼ S29 BT
13" R.Cedar bears N.45°E., 13.9', blazed, scribed ¼ S28 BT
Steel post adjacent to corner.