TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 527)

Set post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on N face; from which
A Fir, 36" dia., bears N.79½°W., 60 lks., mkd: ¼ S BT
A Maple, 20" dia., bears S.45°W., 36 lks., mkd: ¼ S BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12937)

Point for the ¼ sec. cor. of secs. 21 & 28 as determined from the orig. BTs:
A Fir, 42" dia., bears N.79½°W., 60 lks., with an old blaze facing SE, with ¼ cut in bark.
A Maple stump, 20" bears S.45°W., 36 lks., with a decayed blaze on NE face.
At the corner point
Set an iron post, 3' long, 1" dia., 28" in the ground, with brass cap mkd:

¼ S 21 / S 28 / 1952

A Fir, 35" dia., bears N.11°45'E., 155 lks., mkd: ¼ S21 BT
A Cedar, 7" dia., bears S.9°E., 50 lks., mkd: ¼ S28 BT.

William Eimstad - For: International Paper Co. - April 1980 - M 84-77

Found - 15" Cedar, S.9°E., 33.0 ft. S and other marks.
20" Rotten Maple stump, S.36°35'W., 23.76 ft. no marks remaining.
Re-set - 1952 GLO brass cap found buried in slide.
New BT - 9" Fir, S.13°W., 74.5 ft., "¼ S28 BT"
Found - Iron rod, 0.92 ft. SW corner.

Ronald L Rice - Sept. 2016 - Oxbow Timber 1 LLC - C.S. File 65/94-5

Found - 1952 GLO brass cap with the following accessories:
29" R.Cedar bears S.9°E., 33.0' - no marks.
25" rotten Maple stump bears S.36½°W., 23.8' - no marks.
19" D.Fir bears S.13°W., 74.5' - healed face.
Iron rod adjacent to corner
New BTs- 14" D.Fir bears N.32°W., 26.9' - blazed, scribed ¼ S21 BT
19" R.Cedar bears N.70°E. 35.1' -blazed, scribed ¼ S21 BT
Steel post adjacent to corner