TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 518-9)

Set post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on W face; from which
A Cedar, 10" dia., bears N.4¼°E., 110 lks., mkd: ¼ S BT
A Maple, 16" dia., bears S.5½°W., 15 lks., mkd: ¼ S BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12926-27)

The ¼ sec. cor. of secs. 27 & 28 determined at the record bearing & distance from the one remaining BT:
A stump hole of a fallen Cedar bears N.4¼°E., 110 lks., the cedar is badly decayed but shows definite evidence of axe marks on the former S. face.
Definite evidence of a Maple in the SW quad. was not recovered.
At the corner point
Set an iron post, 3' long, 1" dia., 27" in the ground, with brass cap mkd:

¼
S 28 | S 27
1952

from which
A Fir, 50" dia., bears S.55½°E., 71 lks., mkd: ¼ S27 BT
A Cedar, 10" dia., bears N.67¼°W., 83 lks., mkd: ¼ S28 BT

Fd. Ok by W. Eimstad, 4/1980 - M 84-77

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2846, surveyed June 2016 - Nov. 2016 - (DCSO records Vol. 59 Page(s) 23813-4)

The ¼ sec. cor. of secs. 27 and 28, monumented with an iron post, 1" dia., firmly set, projecting 7" above ground, with a brass cap (properly) mkd.
from which the remains of the BTs mkd by Lytle & Norseth in 1952
A fir, 80" dia., bears S.55½°E., 46.9 ft., no marks visible.
A cedar snag, 19" dia., bears N.67¼°W., 54.8 ft., no marks visible.
and a new bearing tree
A fir, 18" dia., bears N.67½°W., 56.4 ft., mkd. ¼ S28 BT.
NAD 1983 (2011)
Lat: 43°53'04.38" N Long: 123°38'21.55" W