TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 509)

Set post, 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on W face; from which
A Fir, 60" dia., bears N.20 3/4°E., 73 lks., mkd: ¼ S BT
A Chinquapin, 10" dia., bears N.88°W., 8 lks., mkd: ¼ S BT

BLM dependent resurvey by Lester E. Fisher & David W. Mattson, Cadastral Surveyors y under Group # 1000 & 1029, Surveyed Jan/Dec. 1980 - (DCSO records Vol. 46 Page(s) 17700-01)

Point for ¼ sec. cor. at proportionate distance; there is no remaining evidence of the orig. corner.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd: T 19 S R 8 W

¼
S 26 | S 25
1980

from which
A Fir, 14" dia., bears N.13°E., 27 lks., mkd: ¼ S25 BT.
A Fir, 24" dia., bears N.78 3/4°W., 39½ lks. mkd: ¼ S26 BT
Set 6 ft. steel fence post alongside the iron post.

Daniel Baker - For: I.P. Co. - April 30, 1985 - M 98-55 - C.S. File 58/289-4K

Bob Cook - For: Roseburg Forest Products - 2/2020 - M176-52

Found - 1980 BLM brass cap up 3" on West slope near top of ridge. A steel post riser is North 1.3 ft.
27" D.Fir N.13°E., 27 lks. with healed face.
20" D.Fir stump N.78°45.W 39.5 lks.