TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by J.H. McClung under Contract #173 dated July 20, 1872 - (DCSO rec. Vol. 2 Page(s) 688-9

Set post for ¼ sec. corner on hillside facing West; from which
A Fir, 16" dia., bears N.28°W., 13 lks.
A Fir, 12" dia., bears S.30°W., 4 lks.

A.H. Hinkson, July 3, 1937 (Rec'd from Lane Co. Surveyor's Office Feb. 20, 1962) C.S. File 53/1-1 & 52/104

Found - BT S.30°W., 4 lks., down & badly rotted
Marked - R.Fir 48" dia., bearing S.65°E. ¼ S30 BT to replace it.
Found - BT N.28°W., 13 lks., had grown over the marks and was hardly visible so I remarked it ¼ S19, BT
Set - 4" maple post 3 ft. high marked ¼ S19 on North side & ¼ S30 on South side.

Douglas Co. Surveyors Office - Milo Godfrey - Vernon Tracy - Clete Putnam - Feb. 1962 - C.S. File 49/89-18

Found - Fir, now 30" N.28°W., 8.6 ft. Tree has been chopped open previously. Good scribing "4" visible on old face. Tree is leaning badly, not uprooted yet, but may not stand long.
Badly decayed snag (Fir) S.30°W., 2.6 ft. Fragmentary but unmistakable scribe marks visible on old face.
Set - Brass cap at cor. mkd:
County Surveyors (Doug) T20S R6W ¼ S19
Office 1962 S30
7" D.Fir N.33°W., 29.7 ft., mkd: ¼ S19 DCS BT.
9" D.Fir S.25°E., 52.6 ft., mkd: ¼ S30 DCS BT.
On county line.

Fd. B.C. & 3 BTs, Donald Peel - June 1991 - M 113-45