TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel under contract 260 dated Apr. 17, 1877 - (DCSO records Vol. 1 Page(s) 313)

Set ¼ sec. post; from which
A fir, 12" dia., bears S.40½°E., 15 lks.
A maple, 6" dia., bears N.62°W., 22 lks.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12518-9

Point for the ¼ sec. cor. of secs. 30 & 31, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼ S 30 / S 31 / 1953

from which
A fir, 54" dia., bears N.25°W., 52 lks., mkd: ¼ S30 BT.
A fir, 24" dia., bears S.12°W., 113 lks., mkd: ¼ S31 BT.

Douglas Co. Surveyors Office - L.E. Monrean - P. L. Earle - Debby L. Stewart - 11/4/1975 - C.S. File 57/39-3

Found - US GLO brass cap, 1953, properly marked.
A fir, 54" dia., bears N.25°W., 34.3 ft. shows good blaze.
Other BTs not found.
Renewal- 50" dia., fir bears S.21½°W., 81.4 ft., scribed "¼ S31 CS BT"
Note - Corner lies approx. N.82°E., & 3/8 mile from last landing on road #20-10-29.1. Corner is approx. 180 ft. east of ridge running S.5°E., & approx. 60 ft. lower than ridge top.

Fd. Ok by Robert Ward, 2/1992 - M 114-48
Fd. Ok by Robert Ward 2/1993 - M116-61