TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias Description
Alias Description
Alias Description
Alias Description

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 590)

Set a sandstone, in place, 40x30x4" above ground which I mark with a cross (x) at the exact corner point for the ¼ sec. cor. marked ¼ on W face; from which
A fir, 28" dia., bears N.86°E., 30 lks., mkd: ¼ S BT.
A fir, 18" dia., bears S.40°W., 21 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - M Godfrey - S.A. Bilow - Nov. 3, 1958 - C.S. File 49/93-5

Found - Stone at corner & mkd. as recorded.
Both orig. BTs:
Orig. 28" now 32" burned & partly rotted Fir snag N.86°E., 19.8 ft. should be N.86°E., 16.8 ft.
Orig. 18" now 20" burned & partly rotted fir snag S.40°W., 13.8 ft.
I find no scribing on either BT. They may have been bark scribed.
I do not set brass cap at corner.
New BTs- 33" R.Fir N.65½°W., 64.0 ft. scribed ¼ S23 CS BT.
15" R.Fir N.61°E., 50.6 ft. scribed ¼ S24 CS BT.

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #1502, surveyed Aug.1989/April 1991 - (DCSO records Vol. 50 Page(s) 19075)

The ¼ sec. cor. of secs. 23 & 24, perpetuated & recorded by Byron in 1958, monumented with the original sandstone, 36x28" (record, 40x30"), firmly set, mkd. X on top & ¼ on W. face, from which the remains of the original bearing trees:
A decayed fir snag, 30" diam., bears N.86°E., 26 lks., no marks visible. (Record, 30 lks.)
A decayed fir snag, 20" dia., bears S.40°W., 21 lks., no marks visible.
and bearing trees mkd. by Byron
A fir, 30" dia., bears N.61°E., 77 lks., with healed blaze
A fir, 45" dia., bears N.65½°W., 97 lks. with healed blaze
At the corner point
Set a brass tablet, 3½" dia., 3¼" stem, cemented flush in drill hole in the center of the X on the corner stone, with top mkd. T20S R7W