TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 5 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T.Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 781)

Set ¼ sec. post, from which
A Fir 15" dia., bears S.8°E., 36 lks. dist.
A Fir 8" dia., bears N.28°W., 59 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 1969 - C.S. File 54/14-28A

Looked for, not found.
Old burn and old logging. No old BTs found.

BLM resurvey by Peter Peterson and Daniel Berry, Cadastral Surveyors under Group #756, surveyed Aug. 1971/June 1972 (DCSO records Vol. 36 Page(s) 15027)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd: T 21 S R 4 W

¼ S 5 / S 8

1972

from which
A Fir 18" dia., bears N.42°W., 80 lks. dist. mkd. ¼ S5 BT
A Fir 18" dia., bears S.5°E., 28 lks. dist. mkd. ¼ S8 BT.