TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias Description
Alias Description
Alias Description
Alias Description

GLO survey by Harvey Gordon and Charles T.Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 764)

Set ¼ sec. post, from which
A Fir 60" dia., bears S.5°E., 58 lks. dist.
A Hemlock 6" dia., bears N.4°E., 50 lks. dist.

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1026, surveyed July 1980/March 1981 - (DCSO records Vol. 44 Page(s) 16964)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: T 21 S R 4 W

¼ S 22
S 27
1980

from which
A Fir 18" dia., bears N.54°E., 26½ lks. mkd. ¼ S22 BT.
A Fir 10" dia., bears S.48°E., 7½ lks. mkd. ¼ S27 BT.

Found OK by D. Edwards, July 2002 - M140-43

BLM dependent resurvey by Harvey M. Christensen, LS 2603, under group # 2171, surveyed Nov. 2007/Aug. 2008 - (DCSO records Vol. 55 Page(s) 21534)

The ¼ sec. cor. of secs. 22 and 27, monumented with an iron post, 2½" dia., firmly set, projecting 6" above the ground, with brass cap (properly) mkd.
from which the remains of the bearing trees mkd. by Jelley and Rogers
A sawed fir stump, 21" dia., bears N.54°E., 17.5 ft. with a healed blaze.

A fir, 17" dia., bears S.48°E., 5.0 ft with a healed blaze and a new bearing tree
A D.Fir, 18" dia., bears S.28¾°W., 17.7 ft., mkd. ¼ S27 BT
No suitable bearing trees available within limits in sec. 22.
Set 5 ft. aluminum fence post alongside cor.