TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T.Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 809)

Set ¼ sec. post, from which
An Oak 8" dia., bears S.2°E., 212 lks. dist.
An Oak 15" dia., bears N.63°W., 550 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Sept. 2, 1965 - C.S. File 54/14-15A

Looked for, not found.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #1059, surveyed April/Dec. 1981 - (DCSO records Vol. 45 Page(s) 17315-16)

The ¼ sec. cor., determined at record bearing and distance from the remaining original bearing tree
An Oak 36" dia., bears N.63°W., 550 lks. with scribe marks ¼ BT visible on overgrowth, and remarked by persons unknown, with scribe marks ¼ S visible on bark blaze.
At the corner point
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 21 S R 5 W
1/4
S 32|S 33
1981

from which new bearing trees
A Fir 24" dia., bears N.63¼°E., 46 lks., mkd. ¼ S33 BT.
A Fir 24" dia., bears N.34°W., 4 lks. mkd. ¼ S32 BT.

Ron Rice, Ward NW, Inc. - For: Seneca Jones Timber Co. 8/2006 - M151-24

Found - 3¼" BLM brass cap dated 1981 with the following accessories:
30" D.Fir bears N.63¼°E., 30.4' - healed face
25" D.Fir bears N.34°W., 2.6' - healed face
36" orig. oak bears N.63°W., 363' - down & rotted
All BTs have red painted band and face plus BT tag.
Galvanized post set adjacent to corner monument.