TOWNSHIP 21 RANGE 9 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 962)

Set Cedar post, 5 ft. long, 4½" sq. 24" in the ground on top of spur sloping E for ¼ Sec. cor. marked ¼ S on the N face, from which

A Fir, 32" dia., bears S.38°45'E., 46 lks., mkd: ¼ S BT.
A Fir, 30" dia., bears N.41°45'W., 70 lks., mkd: ¼ S BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14254)

The ¼ sec. cor. of secs. 9 & 16, determined at record bearing & distance from the orig. BTs:

A rotted Fir stump, 55" dia., bears N.41¾°W., 70 lks., with scribe marks BT visible on opened blaze.
The root hole of a fallen Fir, 50" dia., bears S.38¾°E., 46 lks., with healed blaze.

At the corner point
Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

¼ S 9 / S 16
T 21 S R 9 W
1966

from which

A Fir, 26" dia., bears N.9½°W., 21 lks., mkd: ¼ S9 BT.
A Fir, 15" dia., bears S.5°W., 11 lks., mkd: ¼ S16 BT.

Fd. Ok by L. Roberts Nov. 1981 - M 90-13

Tony Hostetter - For: Roseburg Resources - 7/28/2023 - C.S. File 63/113-13

Found - 1966 BLM brass cap from which:
38" Fir snag, 1966 BT, face evident, BLM tag bears; N.9½°W., 13.9 ft to center
15" Fir stump, 1966 BT, no marks or tag, bears; S.5°W., 7.3 ft to center.

New BTs- 12" Fir, marked "X", BT tag, bears; N.62°41'E., 16.3 ft to spike, placed in root collar below tag.
13" Fir, marked "X", BT tag, bears; S.75°57'E., 5.8 ft to spike, placed in root collar below tag.
10" Fir, marked "X", BT tag, bears; N.72°42'E., 7.7 ft to spike, placed in root collar below tag.

Bearings based on 1965 BLM Survey.