TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 500433

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 15 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1019)

¼ sec. post is a Fir, 18" in dia., from which
A Fir, 16" dia., bears N.87½°W., 15 lks.
A Fir, 20" dia., bears S.84°E., 14 lks.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1091)

Intersect the old ¼ sec. cor., which is a dead Fir, marked & witnessed as described by Surveyor General. I obliterate marks on the old SE BT & change this cor. to refer to Sec. 15 only. Alongside the old cor. set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ Sec. cor., with brass cap mkd:

¼
S 15|
1919

from which
A Fir, 11" dia., bears S.31°W., 23 lks., mkd: ¼ S15 BT. (New BT)
A Fir, 16" dia., bears N.87°W., 15 lks., mkd: ¼ S15 BT. (Old BT)

Herman A. Pieske, RLS #1651 - For: Siuslaw National Forest USDA - Dec. 1983 - M 95-80 A & B

Found - Badly rusted iron pipe filled with concrete (1") no cap found.
20" D.Fir bears S.25°W., 14.9 ft. healed face.
30" D.Fir, uprooted & slid downhill, bears S.74°W., 15.0 ft. (To root wad)

Set - 2½"x30" alum. pipe, 24" in the ground, with 3¼" alum. cap mkd: US Dep of Agri-Forest Service T21S R10W ¼ S15 RLS 1651 1983 Unlawful to Disturb.
28" D.Fir bears N.28°W., 37.0 ft. scribed: ¼ S15 BT, on double blaze.