TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 33; and Sec. 4, T22-11

Alias_____ Description_____
Alias_____ Description_____
Alias_____ Description_____
Alias_____ Description_____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 1858)

Set ¼ sec. post, from which
An Alder 10" dia., bears North, 16 lks. dist.
An Alder 10" dia., bears S.76°W., 12 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 3 Page(s) 1254 (duplicate pg. 1894) and Page 1256 (duplicate page 1896)

At 1/4 sec. point, I make a thorough search for the ¼ sec. cor. which is described as a post with bearing trees but find no trace of the same.
Re-established ¼ sec. cor. at proportionate distance as follows:
Set a post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on N. face, from which
A Fir 12" dia., bears N.82°E., 33 lks. dist. mkd. ¼ S BT.
A Hemlock 10" dia., bears S.46°W., 18 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, John Powell and crew - June 8, 1971 - C.S. File 56/5-20 and M 42-27

This corner set from survey and lies on steep ridge top, ridge running N. & S. Also, creek bears East approx. 195.0'
Set Brass cap at cor. mkd: County Surveyors Office
T21S* R11W ¼ S 33
T22S S 4
1971
*(Note: 11/14/96 per BLM resurvey, cap stamped R12W)
Set steel fence post alongside brass cap.
Bearing Objects:
5/8" Iron rod, N.89°W., 42.7 ft.
5/8" Iron rod, N.89°E., 9.3 ft.

Fd. OK, Nov. 1978 by Thomas Hoesly - M 74-65

Fd. OK, Feb. 1984 by J. Prochnau - M 96-64 A & B

BLM Resurvey by John A. Farmer, Cadastral Surveyor, under Group #1421, surveyed Nov. 1987/Aug. 1994 (DCSO records, Vol. 51 Page 19285

----------(Cont. Next Page)

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 33; & Sec. 4, T22-11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

The ¼ sec. cor. of secs. 4 and 33, reestablished and recorded by James W. Byron, County Surveyor, in 1971, and is accepted as the corner; monumented with an iron pipe, 1¼ ins. diam., firmly set, projecting 18 ins. above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE

T21S R12W* *(Cap stamped wrong, should read R11W)
¼ S 33 / S 4
T22S
1971

from which bearing objects set by Byron

- A rebar, 5/8 in. diam., firmly set, projecting 3 ins. above ground, bears N. 89° E., 14 lks. dist.
- A rebar, 5/8 in. diam., firmly set, projecting 3 ins. above ground, bears N. 89° W., 65 lks. dist.

and new bearing trees

- A chittum, 7 ins. diam., bears S. 38° W., 24 lks. dist., mkd. ¼ S4 BT.
- A fir, 10 ins. diam., bears N. 74 3/4° W., 80 lks. dist., mkd. ¼ S33 BT.

Corner found and used in BLM resurvey by Deborah M. Stephens and Harvey E. Wofford, under group #1521, surveyed April 1990 thru April 1995. (DCSO records Vol. 51 Page(s) 19590)

Fd. Ok on Dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, & Richard Sanford, Surveying Technician, under Group #1644, surveyed April 1992/May 1996. (DCSO records Vol. 53 Page(s) 20187)