TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 700241

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 30 only, T21-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1053)

Set an iron post 3 ft. long, 1" dia., 26" in the ground, for ¼ sec. cor. of sec. 30 only, with brass cap mkd:

¼
│S30
1919

from which
A Fir 16" dia., bears N.44°E., 32 lks. dist. mkd. ¼ S30 BT
A Fir 14" dia., bears S.38°E., 45 lks. dist. mkd. ¼ S30 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - July 18, 1968 - C.S. File 54/1-6

Found - 1919 GLO brass cap, broken off. Concrete filled I.P. in place.
Orig. 16" now 30" Fir, alive, N.44°E., 21.1 ft., shows good scar. We do not open. Rescribe "¼ S30 CS BT".
Orig. 14" now 24" Fir, alive, S.38°E., 29.7 ft. shows good scar. We do not open. Rescribe "¼ S30 CS BT".

Set Brass cap at cor. mkd:

County Surveyors Office
T 21 S R 11 W
¼ │S30 R10W
1968

No new trees marked, none close.
This corner lies about 132 ft. S. of small creek, course SE on very steep NE slope. The E¼ sec. 25 bears South 47.2 ft., record 49.5 ft.