TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 700347

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 19 only, T21-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1055)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ sec. cor. of sec. 19 only, with brass cap mkd: ¼ | S 19 1919

from which
A Fir 16" dia., bears N.31°E., 45 lks. dist. mkd. ¼ S19 BT
A Fir 18" dia., bears S.11°E., 118 lks. dist. mkd. ¼ S19 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - July 18, 1968 - C.S. File 54/1-16

Found - 1919 GLO brass cap, broken off concrete filled I.P. in place.
16" now 34" Fir, alive, N.31°E., 29.7 ft., shows good scar. We do not open. Rescribe "¼ S19 CS BT".
18" now 32" Fir, alive, S.11°E., 77.9 ft., shows good scar. Do not open.

Set Brass cap at cor. mkd: County Surveyors Office T21S R11W ¼ | S 19 R10W 1968

Deposit old pipe alongside.
New BT - 20" D.Fir N.75°E., 63.8 ft. mkd. "¼ S19 CS BT". No other tree close.

This corner lies on very steep S. slope 16 ft. N. of small creek, course E. Across creek there is mouth of small ravine.