TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1448)

Set ¼ sec. post, from which
A Fir 30" dia., bears S.35½°E., 34 lks. dist.
A Fir 30" dia., bears S.14 3/4°W., 55 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C. Putnam, crew - Sept. 7, 1961 - C.S. File 49/143-73

Corner Report Only
Found - 1" Pipe in fence corner (fences N., S., & E.) Also scribed stake mkd. "¼ S R.S."
12" Fir, scribed about 10 years ago, N.56°W., 6.4 ft.
12" Fir, scribed about 20 years ago, S.26½°E., 12.3 ft.
28" W.Fir opened previously, N.10°W., 48.4 ft., faces East, scribed "S" visible in opening, scribed 40 to 45 years ago.
No trace of orig. BTs found.
Small stream is approx. 500 ft. South of cor. as found. (Govt notes call for 6.05 chs.)

S. Kendrick Ford - For: Gus Stores - Feb. 1975 (added to corner report 5/4/2015) - M57-10

Found - 1" iron pipe & stake scribed "¼ S R.S."
Also fd BTs noted Sept. 7, 1961 by Milo Godfrey

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #891, surveyed April/June 1976 (DCSO records Vol. 39 Page(s) 15937-38)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

¼
S 17|S 16
T 22 S R 6 W
1976

from which
A Fir 8" dia., bears N.73½°E., 94 lks. dist. mkd. ¼ S16 BT.
A Grand Fir 5" dia., bears S.64¼°W., 66 lks. dist. mkd. ¼ S17 BT.