TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias Description
Alias Description
Alias Description
Alias Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1527)

Set ¼ sec. post, from which
An Alder 5" dia., bears N.20°E., 16 lks. dist.
A Maple 5" dia., bears N.30°W., 10 lks. dist.

BLM resurvey by John M. Jelley and Donald Beck, Cadastral Surveyors, under Group #590, surveyed July/Aug. 1965 (DCSO records Vol. 33 Page(s) 13952)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: T 22 S R 7 W

¼
S 22|S 23
1965

from which
A Fir 23" dia., bears N.65½°E., 14½ lks. mkd. ¼ S23 BT.
A Cedar 18" dia., bears N.76½°W., 32½ lks. mkd. ¼ S22 BT.

BLM resurvey by Wayne L. Rogers and Lance J. Bishop, Cadastral Surveyors, under Group #1160, surveyed April/July 1984 - (DCSO records Vol. 47 Page(s) 18083)

The ¼ sec. cor., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with 1965 brass cap. from which bearing trees mkd. by Jelley and Beck
A Fir 27" dia., bears N.52°E., 14½ lks. dist. with healed blaze. (Record N.65½°E.)
A Cedar 15" dia., bears N.76½°W., 32½ lks. dist., with fragmentary scribe marks visible on partially healed blaze.

Fd. OK, March 1998 by G. Riley - M 128-33
Fd. Ok by Ken Hoffine - June 2006 - M151-22