TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol 4 Pg 1537)

Set a sandstone 12x10x10 ins., 8" in the ground, for ¼ sec. cor., mkd. ¼ on N. face; from which
An Alder 6" dia., bears N.59°E., 35 lks. dist. mkd. ¼ S BT
A Fir 6" dia., bears S.27°W., 62 lks. dist. mkd. ¼ S BT.
This cor. is on the steep NW. slope of mountain, about 75 ft. above Brush Creek.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C Putnam, crew - April/May 1962 - C.S. File 52/14-106

Found - 48" Fir bears S.26°W., 40.9 ft. This BT shows good scar.
Sandstone, 9" x 10" x 12" set about 9" in ground and mkd. ¼ on N. face.
No trace of other BT.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 7 W
¼ S 25 / S 36
1962
New BTs -18" D.Fir bears N.56°E., 36.1 ft. mkd. ¼ S25 CS BT.
18" D.Fir bears S.33°W., 21.5 ft. mkd. ¼ S36 CS BT.
This cor. is about 6.0 ft. South of creek bottom which bears N.80°W.

FD. Ok by K.Hoffine, Feb. 1995 - C.S. File 63/161-27

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2824, surveyed May 2016/March 2018 - (DCSO records Vol. 59 Page(s) 23872-3)

The ¼ sec cor. of secs. 25 and 36, perpetuated by Godfrey, in 1962, monumented with an iron pipe, 1¼" dia., firmly set, projecting 14" above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree
A decayed fir stump, 55" dia., bears S.19°W., 40.9 ft., with a healed blaze (Record, S.27°W.)
and the remains of the bearing trees mkd. by Godfrey
A fir, 37" dia., bears N.56¼°E., 35.1 ft., with a healed double blaze.
A decayed fir stump, 24" dia., bears S.39¾°W., 21.0 ft., with a healed blaze.
and a new bearing tree
A fir, 12" dia., bears S.2½°E., 12.8 ft., mkd. ¼ S36 BT.