TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 041040

PRIMARY CORNER DESCRIPTION SW cor. Wm. N. Wells DLC #41

Alias 042080 Description SE cor. Edward Griffin DLC #42
Alias Description
Alias Description
Alias Description

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1856

Set post for SW cor. claim 41, from which
A Fir 10" dia., bears N.22°E., 75 lks.
A Fir 10" dia., bears S.12°W., 110 lks.

Ben B. Irving, Co. Surveyor - Milo Godfrey, witness - March 1945 - M 10-72

Location identified from stump of an OBT Fir, which is badly rotted but found scribe marks BT still legible, N.22°E., 75 lks.
Drove a 1/2" x 36" pipe 34" in ground for corner and set new bearing trees:
A W.Oak 6" dia., which bears N.67°W., 79.7 ft.
A B.Oak 4" dia., which bears N.35½°E., 13.2 ft.
(both trees blazed and scribed "SE DLC 42 CS BT")

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13687-88)

The SE cor. DLC #42, identical with the SW cor. DLC #41, perpetuated and recorded by Ben B. Irving in 1945, monumented with an I.P. 1" dia., 8" above ground, firmly set, from which the remaining original bearing tree,
A burned Fir stump 20" dia., bears N.22°E., 75 lks. dist., with no marks remaining.
and trees marked by Irving,
A B.Oak 9" dia. bears N.35½°E., 20 lks with a healed blaze
A W.Oak 11" dia. bears N.67°W. 121 lks with a healed blaze
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 22 S R 8 W
C 42 | C 41
S 23
1963

from which a new bearing tree
A Fir 9" dia., bears S.26°W., 21 lks. mkd. T22S R8W S23 BT
Reset the iron pipe alongside the iron post.

Fd ok by Donald Branch 1/1986 - M 100-31
Found OK by M. Smalley, Dec. 2000 - M132-59
Fd. Ok by J. Estabrook, 1/2008 - M158-3
Fd. BC by N. Hibbs, 6/2021 - 2021-0033B