TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 4 Page(s) 1609-10)

Set a Fir post, from which
A Hemlock 10" dia., bears S.30°E., 13 lks. dist.
A Hemlock 8" dia., bears N.85°W., 25 lks. dist.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967 - (DCSO records Vol. 34 Page(s) 14117-18)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

¼
S 30|S 29
T 22 S R 8 W
1964

from which
A W.Fir 5" dia., bears N.10°E., 38 lks. dist. mkd. ¼ S29 BT.
A Fir 19" dia., bears N.79°W., 21 lks. dist. mkd. ¼ S30 BT

BLM remonumentation by Aaron M Graham, Cadastral Surveyor & Michael O Jones Surveying Tech, under Group No 2241, surveyed Nov. 2008/April 2009 - (DCSO records Vol. 56 Page(s) 22116)

The ¼ sec. cor. of secs. 29 and 30, reestablished by Brooks and Peterson in 1965-67; monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd.
from which the bearing trees mkd. by Brooks and Peterson
A dying fir, 21" dia., bears N.12°E., 24.2 ft., with a healed blaze. (Record, N.10°E., 25.1 ft.)
A decayed fir stump, 27" dia., bears N.70°W., 13.9 ft., with a healed blaze.
and new bearing trees
A fir, 18" dia., bears N.63°E., 16.3 ft., mkd. ¼ S29 BT.
A fir, 6" dia., bears N.13°W., 11.5 ft., mkd. X BT.