TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1570)

Set ¼ sec. post, from which
A W.Oak 24" dia., bears N.84°E., 384 lks. dist.
A W.Oak 24" dia., bears S.66°E., 377 lks. dist.

Douglas County Surveyors Office - Milo E. Godfrey, Deputy - C.S. File 52/14 - Dec. 6, 1962

Corner searched for, not found. Fd. 3/4" x 60" Iron pipe said to be ¼ cor. No BTs found.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13694-95)

The ¼ sec. cor., determined at record bearing and distance from the remaining original bearing tree,
A W.Oak 34" dia., bears N.84°E., 384 lks. dist., with no scribe marks visible on opened and decayed blaze. According to a signed statement furnished by Donald Agee, hereto appended, there were visible scribe marks on the blaze a few years ago. This tree is accepted as the best available evidence of the original corner.
At the corner point
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

¼ S 16
S 21
T 22 S R 8 W
1963

from which
A Fir 10" dia., bears N.26¼°E., 58½ lks., mkd. ¼ S16 BT.
A Fir 12" dia., bears S.54½°E., 100 lks., mkd. ¼ S21 BT.

Mark Smalley - For: Roseburg Resources - 12/2000 - M 132-59

Found - 1963 BLM brass cap on iron pipe.
36" W.Oak, N.84°E., 253.4 ft. down. Orig.
12" Fir, S.54½°E. 66.0' rotten stump, scribe visible
31" Fir, N.26¼°E., 38.6 ft. rotten stump.
New BTs- 14" Fir, N.58°E., 10.3 ft. "¼ S BT"
10" Fir, N.8°W., 45.2 ft. "¼ S BT"
9" Fir, S.40°E., 28.0 ft. "¼ S BT"
8" Fir, S.18°E., 41.6 ft. "¼ S BT"

Found OK by C. Sweeden, Jan. 2001 - M136-34