TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 27 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1566)

Set ¼ sec. post, from which
An Alder 14" dia., bears N.13½°E., 23 lks. dist.
A B.Oak 12" dia., bears S.8°W., 21 lks. dist.

BLM resurvey by Floyd Brooks, Cadastral Surveyor - under Group #436 - surveyed May/June 1962 - (DCSO records Vol. 31 Page(s) 13109-10)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

¼ S 27 / S 34
T 22 S R 8 W
1962

from which
A Fir 7" dia., bears N.4°E., 138 lks. dist. mkd. ¼ S27 BT.
A Fir 4" dia., bears S.38½°W., 84 lks. dist. mkd. ¼ S34 BT.
Corner falls on top of ascent, slopes S.

Fd. and used by BLM in Sec. subd. by Brooks and Jelley, Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records, Vol. 33 Page 13720)

Fd. OK, Sept. 1992, by R. Dolan, M 115-68

David Edwards - For: Beckley Brothers Millman Trust and Roseburg Resources Co. - 1/2014 - M167-12

(Condition report)
Found - BLM brass cap
32" dia., fir bears N.4°E., 91.1 ft.
20" dia., fir bears S.38½°W., 55.4 ft.
Both with healed blaze.