TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 31 (NW Cor. Sec. 32)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 279 survey dated March 5, 1978 (DCSO records Vol. 4 Page(s) 1656)

Set Fir post 4" dia., 4 ft. long, 20" in ground, for corner to secs. 29, 30, 31 and 32, from which,
A Fir 8" dia., bears N.20°E., 18 lks. dist.
A Fir 12" dia., bears S.60°E., 38 lks. dist.
A Fir 10" dia., bears S.45°E., 8 lks. dist.
A Hemlock 8" dia., bears N.62°W., 30 lks. dist.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1700)

The corner to secs. 30 and 31 (31 & 32?), which is a post 30" above ground, 4" sq., firmly set, and marked T22S S29 on the NE.; R9W S32 on the SE.; S31 on the SW. and S30 on the NW. faces, with 1 notch on the S. and 5 notches on the E edges. I obliterated marks on the NE. and NW. faces and added T22S, on the SW. face, from which
A Fir 12" dia., bears S.60°E., 38 lks. dist. mkd. T22S R9W S32 BT.
A Fir 10" dia., bears S.45°W., 8 lks. dist.
The BT in sec. 29 had been blown down, I marked:
A Fir 10" dia., bears N.78°E., 22 lks. dist. mkd. T22S R9W S31-32 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Dec. 1967 - C.S. File 54/60-19

Found - Orig. 12" Fir now 20" snag, 15 ft. high, S.60°E., 25.1 ft., scribe visible on unhealed blaze.
Orig. 10" Fir now 12" shattered stump, S.45°W., 5.3 ft., find reverse "BT".
1894 BT, 10" now 18" Fir, shattered stump, N.78°E., 14.5 ft., find "T22S R9W" scribe.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 9 W
S 31 | S 32
1967

New BTs -10" D.Fir S.65°W., 44.2 ft. mkd. T22S R9W S31 CS BT
24" Hemlock S.43°E., 49.5 ft. mkd. T22S R9W S32 CSBT
18" Hemlock N.69°E., 24.0 ft. mkd. T22S R9W S30 CSBT

This corner lies on spur sloping SE in dense brush and reproduction.