TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 368700

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 33 & 34 only, T21-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1043-44)

Set an Iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 33 and 34, with brass cap mkd:

T21S R10W
S33 | S34
1919

from which

A Fir 22" dia., bears N.54°15'E., 47 lks. dist. mkd. T21S R10W S34 BT.

A Fir 20" dia., bears N.83°W., 64 lks. dist. mkd. T21S R10W S33 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - May 1968 - C.S. File 54/1-27

Found - 1919 GLO brass cap, broken off with concrete filled I.P., in place.

Orig. 22" now 38" Fir, alive, N.54¼°E., 31.0 ft., shows good scar. We do not open. Rescribed "T21S R10W S34 CS BT"

Orig. 20" now 35" Fir, alive, N.83°W., 42.2 ft., shows good scar. We do not open. Rescribed "T21S R10W S33 CS BT"

Set Brass cap at cor. mkd: County Surveyors Office

T21S
T22S R10W S 33 | S 34
1968

We rescribed Orig. BTs because nothing other than Alders close to North. This corner lies on very steep S. slope approx. 175 ft. W. of top of ridge.