TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 1999)

Set ¼ sec. post, from which
A Spruce 24" dia., bears S.40°E., 18 lks. dist.
A Spruce 12" dia., bears West, 13 lks. dist.

Douglas County Surveyors Office - Janet Lundeen, Deputy - R. Smith & S. Flause, - Sept/Dec 1986 - C.S. 62/43-B & M 101-18

Found - 1" dia. Iron bar, no record, 4½ ft. out of ground and in marsh.
1" I.P. bears S.88¼°W., 213.97 ft. (Rec. West 214.01 per M 57-53) Source unknown.
We leave 1" Iron rod as the corner as a replacement monument would not be as stable. As a bearing object, We set 1" (1 3/8" O.D.) x 32" pipe with a 2 3/8" brass cap stamped: Douglas County Surveyors Office BO 1, N.30°E., 42.8 ft. 1986
New Accessories:
18" DBH Spruce bears N.74°W., 49.3 ft. scribed "¼ S7 CS BT" with double blaze.
A 2 3/8" brass cap on a 1⅜" O.D. Iron pipe protruding 4" from ground as BO No 1 marked as above, S.30°W. 42.8 ft
6" Alder bears N.83°W., 5.7 ft. bark scribed "¼ S7 CS BT."
6" Alder bears S.83°E., 3.2 ft. bark scribed "¼ S8 CS BT"
1" I.P. bears S.88¼°W., 213.97 ft. (Rec. West 214.01 ft. M 57-53)

Fd. OK, Sept. 1992 by Ward - M 115-61
Fd. Ok by John Bentley, Oct. 1995 - M 123-4

John Minor - For: Menasha Corp. - Oct. 1998 - M 130-51

Found - 1" iron rod 5 ft. tall on north side of driveway.
Did not find Douglas Co. Brass Cap bearing object: as per the local owner - the cap was there but he covered the area with several feet of fill dirt.
9" Alder S.57°E., (S.83°E.) 3.4 ft.
New BOs- 5/8" x 30" rebar N.78°W., 7.1 ft.
5/8" x 30" rebar S.24°E., 27.1 ft.

DCSO-GIS Corner visitation - 1/27/2004 - Typed: 1/19/2011 - C.S. File 67/33-1

Monument - 1" Comment - OK

Fd. iron bar, by Michael Dado, 4/2008 M155-76