Douglas County Surveyor's Record of Government Corners Renewed

T 23 T. S. R 1 E R. ~~W~~ E W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

A. Vic Cangie
Michael Tompkins
Douglas Co. Surveyor Office
Nov 2, 1976
C.S. 59/26

1

1/4 Corner for Sec. 31 only. West Boundary
Found - 1925 GLO brass cap properly marked.
6" now 15" Fir, bears S.26°E., 18.5 ft. We open and find scribing. Tree alive and well
12" now 34" Fir, bears N.50°E., 39 ft. (Rec. 35.6 ft.) Tree alive and well.
Set - At corner point we reset Iron pipe with brass cap uprooted at site.
New BT - An 8" Fir, bears S.63 1/2°E., 17 ft. scribed 1/4 S31 CS BT with double blaze.
Note: Corner is 50 ft. West of Road 2422 Z.

11/2/76

L. E. Monrean
P. L. Earle
Douglas Co. Surveyors Office
Oct. 26, 1976
C.S. 59/24-44

2

Section Corner for Secs. 25 and 36 only of T23-1W
Found - Stone, 6" x 10" x 8", S25 on NW face, S36 on SW face, four notches on North edge (rec. 5) and one notch on South edge.
5" now 12" Hemlock, bears N.86°E., 24.4 ft. Scribe obliterated in 1925 resurvey.
8" now 16" Hemlock, bears S.23°E., 17.1 ft. (Rec. 18.5 ft.) Scribe obliterated in 1925 resurvey.
8" Hemlock, bears S.6°W., 21.1 ft. uprooted and badly rotted. Scribe mark found "S"
Northwest bearing tree not found.
Set - 30" x 1" Iron Pipe with brass cap at corner point stamped:
"Douglas County Surveyor"

R 1 W	T 23 S S 25 | S 31 S 36 |	R 1 E

1976

We place orig. stone monument on West edge of cap.
New BT - An 8" Hemlock, bears N.35° W., 17.4 ft. Tree double blazed and scribed "T23S R1W S25 CS BT"
There are no suitable trees to scribe in South quad.

10/26/76

Vernon "Ray" Tracy
V. Perron
April, 1970
C.S. 54/27

3

Township Corner: T 23 S / T 24 S R 1 W — S 36 \| S 30 / S 1 \| S 6 — R 1 E

Found - 1922 GLO Brass cap on 3" I.Pipe, out of ground.
Orig. 14" now 22" Fir, Alive, N.60°E., 17.8 ft. shows good scar-tagge
Orig.36",now40" Fir, alive, S.40°E., 39.6 ft. shows good scar, tagged
Orig.40",now46" Fir,alive, S.34 1/2°W.,31.0 ft.Shows good scar,tagged
1922 - 8" Fir, now 8" snag, N.2°W., 41.6 ft. (Rec.N.8°W.) scribe visible on unhealed blaze.
Reset - GLO Brass cap in proper place.
New BT- 28" D.Fir, North 44.5 ft. mkd. "T23S R1W S36 DCS BT"
Note - This corner lies approx. 100 ft. W. of access road from China Creek on very steep, west slope.

3-11

Glenn Baughman
For: U.S. Forest Service.
Dec. 1977
C.S. 65 - 51

4

1/4 Corner for Sec. 36 of T23-1W.
Set - 2 1/2" x 36" I.P. with brass cap marked: T23S R1W R1E 1/4 S36 1977 PLS 536.
BT's - 16" D. Fir bears N.20°E., 17.2 ft. scribed 1/4 S36 BT.
18" D. Fir bears S.63°W., 39.0 ft. scribed 1/4 S36 BT.

12/77

5