TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & 13 of T23-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2340)

Set ¼ sec. post, from which
A Laurel 12" dia., bears S.51°W.,71 lks.
A Fir 14" dia., bears S.49 3/4°E., 85 lks.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12639)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an Iron post, 3 ft. long, 1" dia., 27" in the ground, with brass cap mkd:

¼
S 13|S 18
1943

from which
A Fir 48" dia., bears S.18°E., 153 lks., mkd. ¼ S18 BT.
A Fir 36" dia., bears N.29½°W., 82 lks., mkd. ¼ S13 BT.

Fd. OK, March 1994, D. Baker, M 118-60

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/August 22, 1995 - (DCSO records Vol. 51 Page(s) 19459)

The 1/4 sec. cor., monumented with an iron post, 1 in. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

1/4
S 13 | S 18
1943

from which the remains of bearing trees mkd. by Gould, Gawron, and Eggen
A fir, 64" dia., bears S.18°E., 155 lks. with healed blaze
A sawed fir stump, 36" dia., bears N.30°W., 84 lks., with healed blaze. (Rec. N.29½°W., 82 lks.)
and a new bearing tree
A fir, 8" dia., bears N.59½°W., 8 lks., mkd. ¼ S13 BT.

Mark Smalley - Roseburg Forest Products - 4/3/2007 - C.S. 65/60-16

Found - 1943 BLM IPBC
64" Fir stump S.18°E., 153 lks., rotten continued

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & 13 of T23-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New -	36" Fir stump N.30°W., 84 lks., rotten 8" Fir N.59½°W., 8 lks., did not find. 12" Fir N.62°W., 12.1 scribed "¼ S BT" 11" Fir S.42°W., 23.8 scribed "¼ S BT" Compass decl. 16½°E.