TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2380)

Set ¼ sec. post, from which
A Fir, 30" dia., bears N.23°E., 65 lks.
A Fir, 20" dia., bears N.17°W., 131 lks.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Deputy and crew - C.S. File 54/16-57 (date 1969)

Corner not found.
No OBTs found. Old fence cor S of cor according to line calls

---

Dan Baker - For: Weyerhaeuser Co.- 11/1994 - M 121-16

Set - 1¼" x 36" iron pipe with 2½" brass cap dated 1994, mkd:

T23S R5W
¼
S 7 | S 8
PLS 1978
1994

11" Fir, N. 50°W., 24.3 ft., scribed "¼ S7 BT"
9" Fir, N.33°E., 23.5 ft., scribed "¼ S8 BT"
12" Fir, S.66°E., 35.9 ft., scribed "¼ S8 BT"
15" Fir, S.54°W., 7.1 ft., scribed "¼ S7 BT"
6 ft. alum. post 1 ft. north.

Note- The following Douglas Co. Rd. #24 R/W monuments are provided to assist. in locating the corner position:
3/4" rebar, N.39°W., 365 ft. - "CRW PC"
5/8" rebar, N.37°W., 340 ft. - CRW PT"
BTs established in this survey were based on Magnetic 20° declination, with distances to a "W" spike in the lower blaze.

Fd. & used on BLM dependent resurvey by Wayne Rogers & Bryan Seibold, Cadastral Surveyors, under Group #1832 surveyed July - Oct. 1997 - (DCSO recs. Vol. 53 Pg(s) 20283)

DCSO-GIS Corner visitation - 11/30/2005 - Typed: 1/20/2011 - C.S. File 67/33-1

Monument - 1½" BC/IP Comment - ok, 4 live BTs