TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO recs Vol 8 Pg 2566)

A Fir root 4 ft. high, 8" dia., which I mark ¼ S on W. side for ¼ sec. cor., from which
A Fir 30" dia., bears S.56°E., 82 lks. dist. mkd. ¼ S BT
A Fir 40" dia., bears N.62°W.,156 lks. dist. mkd. ¼ S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan. 1966 - C.S. File 54/12-43

Found - Orig. 30" now 44" Fir, turned out and lying nearly face down, S.56°E., 54.1 ft. Open and find "BT" scribe and reverse, We use center of stump hole.
Possible orig. NW. BT, down and slid out of position, nearly buried. We measure from corner South to creek, 195 ft., orig. call is 198 ft.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
¼ S 27|S 26
1966

New BTs- 17" D.Fir S.12°E., 16.5 ft. mkd. ¼ S26 CS BT.
11" Cedar N.62°W., 37.5 ft. mkd. ¼ S27 CS BT.

This corner lies on SW. slope on new and old N-S blazed line.

Ronald L Rice - For: Oxbow Timber 1 LLC - Jan. 2015 - M169-7

Found - No monument found due to slide.
One down BT remaining all others lost to slide.
Reset corner monument at record bearing and distance from the root hole of the one remaining tree.

Set - 5/8"x30 REBAR WITH 2½" aluminum cap mkd
T23S R8W
¼
S27|S28
2015
54633LS

Root hole of 11" Cedar bears N.62°W., 37.5' - cast over high stump with tag and buried face

New BTs- 9" D.Fir bears S.10°W., 34.0', blazed, scribed at base X BT
13" D.Fir bears S.80°W., 34.0', blazed, scribed ¼ S27 BT
13" D.Fir bears N.49°W., 14.7', blazed, scribed ¼ S27 BT
9" D.Fir bears S.16°E. 3.6', blazed scribed ¼ S26 BT
No suitable bearing tree in the ne quadrant

Steel post adjacent to corner