TOWNSHIP 23 RANGE 10 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Levi C. Walker under contract #763, dated Aug. 23, 1905 - (DCSO records Vol. 7 Page(s) 2736)

Set fir post, 3' long, 4" sq., 24" in the ground, for cor. of secs. 2, 3, 10 & 11, marked T23S S2 on NE, R10W S11 on SE, S10 SW, & S3 on NW face, with 5 notches on S and 2 notches on E edge; from which

An Alder, 6" dia., bears N.55°E., 4 lks., mkd: T23S R10W S2 BT.
An Alder, 7" dia., bears S.75°E., 15 lks., mkd: T23S R10W S11 BT.
A Fir, 6" dia., bears S.43°W., 22 lks., mkd: T23S R10W S10 BT.
A Fir, 4" dia., bears N.25°W., 28 lks., mkd: T23S R10W S3 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - S. Bilow - For: "West Shore Lodges Subdivision, Mr. Rose & Mr. Lee - Feb/May 1958 - M 8-72 & C.S. 49/90 (pg 8)

Found - Orig. 4", now 14" Fir N.25°W., 18.5 ft., I open & find good scribing "3"
Also find 30" Fir that checks bearing & dist. for orig. SW BT.

Set - Brass cap mkd: County Surveyors Office 1958 — S 3 | S 2 / S 10 | S 11 T23S R10W

New BTs- 10" R.Fir N.49°E., 16.5 ft., mkd: S2 T23S R10W CS BT
10" R.Fir N.80°W., 16.8 ft., mkd: S3 T23S R10W CS BT
30" R.Fir S.50°W., 14.3 ft. mkd: S10 T23S R10W CS BT
11" Myrtle S.58½°E. 40.9 ft mkd: S11 T23S R10W CS BT

James McIntosh, Oregon Dept. of Forestry - 7/2010 - M161-15

Found - DCSO 1½" galvanized iron pipe & bronze cap, 1958 (now 16" above ground in place)
4" Fir (orig.) N.25°W., 28 lks. (Now 14"x2' high rotted stump in place, axe work visible)
10" Fir N.49°E 16.5' (now 26" in place, face closed, BLM BT Tag)
10" Fir N.80°W., 16.8' (now 21" in place, face closed, BLM BT Tag)
30" Fir S.50°W., 14.3' (now 55" in place, face closed, BLM BT Tag)
11" Myrtle S.58½°E., 40.9' (now 13" in place, face rotted, axe work visible)