TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2809)

Set a basalt stone, 12x10x6", 8" in the ground, for cor. of secs. 2, 11, 10, & 3 marked with 5 notches on S & 2 notches on E edges, from which

A cedar, 24" dia., bears N.65°E., 44 lks., mkd: T24S R1W S2 BT.
A fir, 24" dia. bears S.45°E. 48 lks. mkd: T24S R1W S11 BT
A fir, 24" dia. bears S.72°W. 50 lks. mkd: T24S R1W S10 BT
A fir, 30" dia. bears N.8½°W., 44 lks. mkd: T24S R1W S3 BT

This cor. is on a steep hillside, sloping W, about 100 ft. above creek.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Terry Connell - June 1965 - C.S. File 52/42-34

Found - All 4 orig. BTs alive & in good condition & 2 stones with no marks on them. Distances to BTs was apparently taken on slope from the face.
Orig. 24" now 39" Cedar N.65°E., 29.0 ft. (slope) mkd: "T2 R1 S2 BT" on partially healed scar.
Orig. 24" now 29" Fir N.45°E. 31.7 ft. (slope) shows good scar.
Orig. 24" now 30" Fir S.72°W. 33.0 ft. (slope) shows good scar.
Orig. 30" now 36" Fir N.8½°W. 29.0 ft. (level) very good scar.

Set - Brass cap at cor. mkd: County Surveyors Office 1965 T24S R1W

S 3	S 2
S 10	S 11

No new BTs marked.

This corner lies on steep west slope approx. 300 ft. E of rd.

FD. Ok by DCSO Dec. 17, 1996 - C.S. File 64/71-6