TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T24-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 7 Page(s) 2948)

Set ¼ sec. post, from which
A Hemlock 12" dia., bears S.35°E., 24 lks. dist.
A Hemlock 12" dia., bears S.88°W., 26 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew March 1968 - C.S. File 54/27-145

Found - 1/2" I.P. set at corner and "W" method BT, unrecorded.
Orig. 12" now 14" Hemlock S.35°E., 15.8 ft., now down and out of position, we find probable stump hole, face rotted, no scribe.
Orig. 12" now 14" Hemlock S.88°W., 17.2 ft., now stump, leaning, "BT" scribe visible on previously opened blaze.
30" D.Fir stump S.48°W., 15.0 ft. "W" nail, we mark "¼ S24 CS BT".

Set Brass cap at cor. mkd. County Surveyors Office
R T 24 S R
3W ¼ S 24 S 19 2W
1968

New BT - 20" Cedar stump S.28°E., 40.1 ft. mkd. ¼ S19 CS BT.
Corner lies on moderate NW. slope changing to very steep NW. slope.