TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 400107

PRIMARY CORNER DESCRIPTION NE Cor. TR. 37 (Sec. 33)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13295)

Point for the NE cor. of Tract No. 37, sec. 33.
Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked: T 24 S R 2 W

S 33 | S 34
TR 37 | TR 38
1963

from which
A cedar, 11" dia. bears S.66½°W., 30 lks. mkd: TR37 S33 BT
A hemlock, 11" dia., bears N.19°W., 7 lks., mkd: S33 BT.

Howard Johnstone - For: Roseburg Lumber - 2/7/1979 - C.S. File 58/188-1

Found - 1963 Cadastral brass cap on iron pipe mrk T24S R2W Sec. 33 TR 37 Sec. 34 TR 38.
11" Cedar S.66½°W., 19.8 ft., broken off above visible scribe.
11" Hemlock N.19°W., 4.6 ft. down.
New BTs- 12" Cedar, N.72°W., 27.0 ft., "TR37 S33 BT"
8" Hemlock, S.19°W., 36.2 ft., "TR37 S33 BT"

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 11/25/2025 - C.S. File 67/61-42

Found - 3¼" BLM brass cap buried 4". Oriented E-W.
Sawn, burnt, rotted 22" x 1½ ft. cedar stump N.68°W. 27.0 ft. (Rec. N.72°W.) Blaze burnt away.
Sawn, burnt, 14" x 1½ ft. hemlock stump S.15°W. 35.7 ft (Rec S.19°W. 36.2 ft.) partly healed blaze burnt. No scribes found.
New - Sawn, burnt 14" x 1 ft. fir stump N.59°E. 7.7 ft. 3½" mag nail top center.
Sawn, burnt 18" x ½ ft. fir stump S.38°E. 28.7 ft. 3½" mag nail top center.
Notes - Area burnt badly 9/2020.
Mon in recent clearcut on moderate ground. Old forest in N.W. quadrant. Burned mon. is approx. 100 ft west of north end of short gravel spur rd.
Compass decl. 14¼°E.
TRIMBLE GEO XT POSITION
43.43579663 N. 122.93240243 W.