TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 3007-8)

A hemlock post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ sec. cor. mkd. ¼ S on W face from which
A fir, 24" dia., bears N.41°W., 5 lks., mkd: ¼ S BT.
A cedar, 16" dia., bears S.59°W., 54 lks., mkd: ¼ S BT.

BLM dependent resurvey by Norman D. Price, Cad. Engineer, under Group 242 surveyed June/Aug. 1950 (DCSO recs. Vol. 27 Page(s) 11483-4)

The ¼ sec. cor of secs 19 & 20 determined at the record bearing & dist from each of the orig BTs which stand as follows
A dead fir, 30" dia., bears N.25°E., 5 lks., mkd. on bark ¼ S BT. (Rec. bearing N.41°W.)
An I.Cedar, 20" dia., bears S.62°W., 54 lks., mkd. ¼ S BT. (Rec. bearing S.59°W.)
At the corner point
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked: ¼
S 19|S 20
1950
from which
A fir, 12" dia., bears N.62¼°E., 43 lks., mkd: ¼ S20 BT.
A I.Cedar, 36" dia., bears S.46¼°W., 82 lks. mkd: ¼ S19 BT

Adam DeGroot - For: Weyerhaeuser Co. - May 2020 - M178-2

Found - A 1" iron post, by Price in 1950 per the USBLM Dependent Resurvey, firmly set and projecting 14" above ground, with a 2½" brass cap properly marked per the record.
From which remains of an 1883 BT by Wheeler:
A 24" rotted D.Fir stump bears N.22°45'E., 4.5 ft w/no mks. (N.25°E., 5 lks)GLO 1883, BLM 1950
The remains of an 1950 BT by Price:
A 20" rotted D.Fir stump bears N.62°15'E., 28.5 ft w/no mks. (N.62¼°E., 43 LKS) BLM 1950
New - A 15" D.Fir bears S.69°45'E., 39.8 ft scribed "¼ S20 BT" on dbl blaze.
A 13" D.Fir bears N.77°45'W., 34.1 ft scribed "¼ S19 BT" on dbl blaze.
A ⅝"x30" iron rod W/2" BTs alum. cap stamped "RM 1 2020" bears N.6618'37"E., 27.05 ft.
A ⅝"x30" IRON ROD W/2" BTs alum. cap stamped "RM 2 2020" bears S.29°36'13"W., 23.25 ft
Note - Corner falls ±40 ft North of ridge top road