TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2954)

Set ¼ sec. post from which
A fir, 10" dia., bears N.5°E., 40 lks.
A fir, 7" dia., bears S.28°E., 40 lks.

BLM dependent resurvey by Norman D. Price, Cad. Engineer, under Group 242 surveyed June/Aug. 1950 (DCSO recs. Vol. 27 Page(s) 11474)

Point for the ¼ sec. cor. of secs. 16 & 21, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼ S 16 / S 21 / 1950

from which
A fir, 26" dia., bears N.7½°W., 53 lks., mkd: ¼ S16 BT.
A fir, 14" dia., bears S.48¼°E., 41 lks., mkd: ¼ S21 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Sept. 1967 - C.S. File 54/27-91

Found - 1950 GLO brass cap, properly mkd., in pile of logging debris, out of position approx. 15.0 ft.
Straighten pipe & reset from stumps of BT, as follows:
26", now 28" Fir, 5 ft. high stump, N.7½°W., 35.0 ft., open & find "4 S16 BT" scribe.
SE BT down & out of position.
New BTs- 16" Hemlock, N.5°W., 40.8 ft. mkd: ¼ S16 CS BT.
18" Maple S.11°W., 63.2 ft., mkd: ¼ S21 CS BT.
Note - This corner lies in old cat skid road on bench.

Donald Peel, LS 752 - For: Weyerhaeuser Co. - Jan, 31, 1986 - M100-29

Found - 1" IP with GLO brass cap "1950"
18" triple maple, S.10½°W. 63.3 ft. (center measure)
30" fir stump, N.7½°W., 34.5 ft. (face measure)
SE BT now uprooted & down.
New BT - 13" fir, N.39½°E., 30.4 ft. scribed ¼ S16 BT (dist. to "W" nail)

Fd. Ok by D. Baker, 11/2000 - M136-37
FD. BC by D. Baker - 10/2009 - M160-23