TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 3002)

Set hemlock post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ sec. cor. mkd. ¼ S on N face from which
A fir, 18" dia., bears N.10°W., 61 lks., mkd: ¼ S BT.
A chinquapin, 10" dia., bears S.21°E., 35 lks. mkd: ¼ S BT

BLM dependent resurvey by Norman D. Price, Cad. Engineer, under Group 242 surveyed June/Aug. 1950 (DCSO recs. Vol. 27 Page(s) 11477)

Point for the ¼ sec. cor. of secs. 9 & 16, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼ S 9 / S 16 / 1950

from which
A maple, 10" dia., bears N.16½°E., 8 lks., mkd: ¼ S9 BT.
A fir, 60" dia., bears S.62°E., 59 lks., mkd: ¼ S16 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Sept. 1967 - C.S. File 54/27-83

Found - 1950 GLO brass cap, firmly set, & properly marked.
10", now 11" maple, N.16½°E., 5.3 ft., tipped over, alive, shows scribe "¼ S9" on unhealed blaze.
60" fir stump S.62°E., 38.9 ft., shows healed blaze.
Set - 6.0 ft. steel fence post 2.0 ft. East of corner, from which:
16" Hemlock stump S.66°W., 14.4 ft., mkd: "¼ S16 CS BT" (6 ft. high stump)
Note - This corner lies on gentle SW slope in logged off unit.

Robert Cook - For: Weyerhaeuser Co. - 12/2010 - M161-57

Found - 1950 GLO brass cap on ¾" pipe up 6" in ferns about 75 ft. north of a gravel road. Steel fence post east 2.0 ft.
60" D. Fir stump (S62°E 38.9 ft.) with tag & paint.
New - 15" D. Fir forked N.80°W 15.6 ft scribed "¼S9" above "BT"
14" D.Fir by road S.25°E 52.8 ft. scribed "¼S16" above "BT".
60d nail for control lies on S side of road S.41°51'15"W 122.97 ft.