TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Oscar F. Thiel, Contract #658, May 1896 (DCSO records Vol. 7 Page(s) 3070)

A point 400 ft. below top of mountain, I set a Fir post 3′ long 3" sq. 24" in the ground for ¼ sec. cor. mkd: ¼ S on the N face from which:

A Fir, 10" dia., bears N.6°W., 5 lks., mkd: ¼ S BT.
A Fir, 24" dia., bears S.25°E., 39 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office -Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - Feb/March 1963 - C.S. File 53/9-28

Found - 33" Fir, S.25°E., 25.7′, uprooted & down, not recent. Opened scar & fd. good scribing "¼"
12" Fir, N.6°W., 3.3′, shows good scars. Did not open.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE
T24S R4W ¼ S4/S9 1963
22" D.Fir, S.37°E., 39.2′, mkd: ¼ S9 CS BT

BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #979, surveyed May/Sept. 1979 (DCSO records Vol. 42 Page(s) 16401)

The ¼ sec. cor., perpetuated & recorded by Godfrey in 1963, monumented with an iron post, 1¼" dia., firmly set, projecting 4" above ground, with brass cap properly mkd.
from which the remains of the orig. BT

A root hole, bears N.6°W., 5 lks., with a down fir alongside, 15" dia., with healed blaze.
A root hole, bears S.25°E., 39 lks., with a down fir alongside, 33" dia., with fragmentary scribe marks visible on open blaze.

and the remains of a bearing tree mkd. by Godfrey

A root hole, bears S.37°E., 59 lks. with a down fir alongside, 25" dia., with healed blaze.

and new BTs

A Chinquapin, 6" dia., bears N.4½°E., 22½ lks., mkd: ¼ S4 BT on bark blaze.
A Chinquapin, 9" dia., bears S.42½°E., 15½ lks., mkd: ¼ S9 BT on bark blaze.

Fd. & used in BLM dependent resurvey by Lance J. Bishop & James L. White, Cadastral Surveyor, under Group 1233, surveyed Oct. 1984/Jan. 1985(DCSO records Vol. 47 Page(s) 18026)