TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 7 Page(s) 3030)

Set ¼ sec. post from which
A Fir, 10" dia., bears S.85°W., 13 lks.
A Fir, 50" dia., bears S.53°E., 36 lks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - March 1963 - C.S. File 53/9-55

Reported as not found.
Cruiser marks on burned cedar snag.

BLM dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, under Group #1448, surveyed July/Aug. 1988 (DCSO records Vol. 49 Page(s) 18666-67)

Point for the ¼ sec. cor. at proportionate distance; there is no remaining evidence of the orig. corner.
Set a stainless steel post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd: T24S R4W

¼
S 3 | S 2
1988

from which
A Fir, 14" dia., bears S.79½°E., 54 lks., mkd: ¼ S2 BT.
A Fir, 10" dia, bears S.12°W., 7½ lks., mkd: ¼ S3 BT.
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2168, Surveyed May/Nov. 2007 - DCSO records Vol. 57 Page(s) 22605-6

The ¼ sec. cor. of secs. 2 & 3, monumented with an iron post, 2½" dia., firmly set, projecting 3" above ground, with brass cap (properly) mkd.
from which the remaining bearing tree mkd. by Peterson
A fir, 18" dia., bears S.79½°E., 35.6 ft., with a healed blaze.
and new bearing tree
A fir, 11" dia., bears S.75¼°W., 4.0 ft., mkd. ¼ S3 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.