TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 039030

PRIMARY CORNER DESCRIPTION SSW Cor. Allen DLC #39

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DLC Survey by - Addison R. Flint, Under Contract #28, dated April 1854

Set post in cultivated ground. Deposited stone 4 x 6, raised mound with trench as per instructions.

F.C. Frear, Douglas Co. Surveyor - Wit: H.L. Eppstein and H.C. Crocker - Sept 29-30, 1919 - Field Book 47 Pages 1-13 (and "old" corner book, page 44)

Reestablished corner by setting a 10" x 10" x 36" sandstone rock, from which
A 12" W.Oak bears S.35°E., 1.525 chs., CS BT.

Not found, DCSO, V.Tracy, April 1970 C.S. File 49/124-102

Survey by W.S. Barnes - For: Keith Pedersen - Sept. 1976 - M 61-58

Found - DLC corner stone, dug out and moved.
Set 5/8" I.P. at projected fence cor. for DLC cor. per instructions from D.R. Mask, Oakland, Oregon.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - Kody Inda - 9/9/2007 - C.S. File 67/24-21

Fd. ¾" I.D. iron pipe 4" under surface of graveled rd.