TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 039040

PRIMARY CORNER DESCRIPTION SE Cor Allen DLC #39

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

DLC Survey by - Addison R. Flint, Under Contract #28, dated April 1854

A Stone 7 x 3 inches with mound as per instructions.

F.C. Frear, Douglas Co. Surveyor - Wit: H.L. Eppstein and H.C. Crocker - Sept. 29-30, 1919 - Field Book 47 Pages 1-13 (and "old" corner book, Page 44)

Reestablished corner by setting an 8" x 10" x 18" rock, from which
A 10" W.Oak bears S.38°W., 31 lks., CS BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Vince Perron, crew - April 10, 1970 - C.S. File 49/124-103

Found - Corner stone by Frear, with faint chisel marks.
10" now 26" W.Oak, alive, S.38°W., 20.5 ft., rehealed scar, opened quite a few years ago.
Rescribe "SE DLC 39 CS BT"
Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 5 W
SE DLC 39 /
1970
New BT - 14" W.Oak S.2°E., 64.3 ft. mkd. SE DLC 39 CS BT.
Reset old stone alongside brass cap.
Corner falls at fence corner about 300 ft. W. of gate across old Hwy. #99.

Fd. OK, May 1984, R. Ware, M 97-79