TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 31; & 6 of T25-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, contract #31 dated April, 1853 (DCSO records, Volume 8 Page 3133)

Set ¼ sec. post, from which
A Fir 15" dia. bears S.11¼°W., 83 lks. dist.
A Fir 18" dia. bears N.19°W., 108 lks. dist.

Bureau of Land Management Dependent Resurvey, August-Sept. 1967 - Lynn Roseberry - (DCSO records, Volume 36 Page 14940)

There is no remaining evidence of the original corner.
Set an iron post, 28" long 2½" dia. 24" in the ground, with brass cap marked: T 24 S R 6 W

S 31
¼ S 6
T 25 S
1967

from which
A Fir 15" dia. bears N.14 3/4°W., 110 lks. dist. mkd ¼ S31 BT.
A Fir 30" dia. bears S.32°W., 48 lks. dist. mkd. ¼ S6 BT.
This corner falls on a spur, slopes SE.

Bruce Shaner Engineering - For: Western Timber Company
July 28, 1989 - RM 3-72 & C.S. File 63/96

CORNER REPORT ONLY
Found - 2½" Iron pipe with a 3¼" brass cap.
18" D.Fir face overgrown, bears N.14¾°W., 72.6 ft.
30" D.Fir, face overgrown, bears S.32°W., 29.2 ft.
(Record, 31.7 ft.)
The corner is North approx. 80 ft. from the top of a spur ridge that slopes down to SE. Many mistakenly blazed property lines and BTs in the area South of corner approx. 100 ft.

Mark Smalley - For: Roseburg Forest Prod. - 9/21/93 - C.S. 63/153-38

Found - 1967 BLM BCIP
Fir, 18", N.14 3/4°W., 72.6 ft.
Fir, 30", S.32°W., 29.2 ft.
New Accessories -
Fir, 30", N.65°W., 70.5 ft., scribed "¼ S31 BT"
Fir, 12", N.79°E., 26.9 ft., scribed "¼ S31 BT"