TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 6 of T25-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, Contract #73 dated June 8, 1857 (DCSO records, Vol. 8 Page 3194)

Set ¼ sec. post, from which
An Oak 15" dia., bears South, 13 lks. dist.
An Oak 18" dia., bears N.10°W., 19 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy - Milo Godfrey; Clete Putnam - Marcy 25, 1960 - C.S. File 49/41-27

Found - Orig. 18" now 26" B.Oak, center partly rotted, shows good scribing (reverse)
Orig. South BT gone. Set Brass cap at cor. mkd. County Surveyor's Office, 1960

¼ S 31 T24S
S 6 T25S R 7 W

New BTs - 6" R.Fir bears S.34°E., 9.4 ft. scribed ¼ S6 CS BT.
5" R.Fir bears N.70°E., 9.0 ft. scribed ¼ S31 CS BT

Fd OK, Howard Johnstone, May 1987 - M 104-16

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 2/18/98 - C.S. File 64/79-33

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 6" above ground. 1960
18" now 26" dia. B.Oak with a previously opened unhealed rotted blaze bears N.10°W., 12.5 ft (Agrees with rec.) OBT
5" now 20" dia. D.Fir with a fully healed double blaze, bears N.70°E., 9.0 ft. (Agrees with rec.) 1960
6" now 6" dia., down D.Fir with a rotted blaze, roothole near record, "S.34°E., 9.4 ft" 1960
16" D.Fir with a fully healed single blaze bears S.29°W., 14.5 ft. (Agrees with Roseburg Lumber BT Tag dated 4-8-87 by F. White) This BT is not of record.
New BT - 11" dia. D.Fir, double blazed and scribed "¼ S31 CS BT" bears N.69½°W., 17.3 ft.

Fd. & used on BLM dependent resurvey by Bryan S. Seibold & Wayne Rogers, Cadastral Surveyors, under Group #1862, surveyed Sept.-Dec. 1997 - (DCSO recs Vol. 53 Page 20303)