TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3219)

---

Set ¼ sec. post, from which
An Oak 40" dia., bears S.85°E., 60 lks. dist.
An Oak 40" dia., bears N.10°W., 32 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - and crew - May 1963 - C.S. File 49/41-53

---

Found - 44" W.Oak, N.10°W., 21.1 ft., opened scar and found good scribing "S". Tree rotten in center, appears to be dying.
Uprooted Oak, near location for SE. tree, S.85°E., 39.6 ft. Cannot determine exactly where tree stood. Found good reverse scribing "¼S"

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 7 W
¼ S 8 / S 17
1963

New BTs- 10" D.Fir N.47°W., 36.2 ft. mkd. ¼ S8 CS BT.
10" D.Fir S.45°E., 17.0 ft. mkd. ¼ S17 CS BT.

Corner lies in fence corner, fences South and East from corner. Also fence posts continuing North from corner.

Fd. and used in BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #889, surveyed Oct. 1975/April 1976 -(DCSO records Vol. 40 Page(s) 16009)

Found OK by K. Hoffine, July 2001 - M138-42