TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3212)

Marked a Fir 8" dia., from which
A Fir 7" dia., bears N.80°W., 15 lks. dist.
A Laurel 10" dia., bears S.34°W., 32 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Jan. 25, 1956 - C.S. File 47/91

Corner renewed from 8" Fir now 16", rotted Fir stump found scribed "S" and lower part of 1 scribed on N. side. This is tree originally marked for ¼ corner.
Set an iron pipe with brass cap mkd: County Surveyors Office

T24S R7W
¼ S 9 / S 16
1960

Set the pipe with brass cap at N. side of stump. Mound of rock and stone place.
Blazed and scribed:
18" Cedar S.53¼°E., 142.5 ft. mkd. ¼ S16 CS BT.
14" Cedar N.82°W., 15.2 ft. mkd. ¼ S9 CS BT.

Found OK by D. Edwards, May 2000 - M134-70

BLM resurvey by A. Bert Skeesick Cadastral Surveyor under Group #2037, surveyed Feb/March 2003 - (DCSO rec. Vol. 55 Page(s) 21301-2)

The ¼ sec. cor. of secs. 9 & 16, perpetuated by DCSO in 1956, from evidence no longer in existence, monumented with an iron post, 1¼ ins. diam., firmly set, projecting 16 ins. above ground, with brass cap (properly) mkd.
from which the remaining BT mkd. by the DCSO
A cedar, 43" dia. bears N.88½°W. 15.2 ft. w/healed blaze and new bearing tree
A fir, 20" dia., bears N.4½°E., 27.5 ft., mkd. ¼ S9 BT.
(MAG-NAIL driven into left side of tree)
Corner lies 2.3 ft. North of wire fence, bears E. and W.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

---