TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3279-80)

I set a post 4" sq., 4 ft. long, 24" in the ground for ¼ sec. cor., marked ¼ S on N., from which

A Fir 14" dia., bears N.62°E., 23 lks. dist. mkd. ¼ S BT.

A Cedar 30" dia., bears South 48 lks. dist. mkd.¼ S BT.

I destroy original ¼ cor. and continue E.

(Note: On page #3257, DCSO records, Whipple ran line but no ¼ corner described. No previously set cor. desc. found. V.Laugen, Feb. 1997)

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - Nov. 1957 - C.S. File 49/41-2

Found - Orig. 30" now 40" Cedar, South 31.7 ft., has open face, good scribing "¼S"

Orig. 14" now 24" (rec. Fir, should be Hemlock) N.62°E., 15.2 ft., shows good face, I do not open

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 7 W
¼ S 4 / S 9
1957

I reblaze and rescribe the orig. South BT, "¼ S9 CS BT". Distance should be 33.2 ft.

Fd. OK, Feb. 1980 by L. Roberts - M 84-57

BLM resurvey by A. Bert Skeesick Cadastral Surveyor under Group #2037, surveyed Feb/March 2003 - (DCSO rec. Vol. 55 Pages 21307-8)

The ¼ sec. cor. of secs. 4 & 9, perpetuated by the DCSO, in 1957, monumented with an iron post, 1¼" dia., firmly set, projecting 7" above ground, with brass cap (properly) mkd from which the remains of the original bearing trees.

A decayed hemlock stump, 24 dia., bears N.66¼°E., 14.0 ft. with a healed blaze. (Record, fir, N.62°E., 15.2 ft.)

A cedar, 47" dia., bears South, 32.7 ft., with a healed blaze. (Record, 31.7 ft.)

and new bearing tree

A fir, 8" dia., bears N.58¼°W., 16.8 ft., mkd. ¼ S4 BT

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description