TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3326-27)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which

A Cedar 10" dia. bears S.21½°E.,1 4 lks. dist. mkd. ¼ S BT

A Cedar 24" dia., bears N.8°W., 18 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - W. Penley; J. Heritage, crew - C.S. File 54/55-27 - March 8, 1971

Corner searched for, not found.
No trace of corner. Major fire in area at one time.

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1241, Surveyed April/May 1986 - (DCSO records Vol. 47 Page(s) 18123)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: T 24 S R 8 W

¼
S 34 | S 35
1986

from which

A Cedar 15" dia., bears N.50°E., 18 lks. dist. mkd. ¼ S35 BT.

A Fir 13" dia., bears S.76°W., 32 lks. dist.mkd. ¼ S34 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.