TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 6; & 31 of T24-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records, Volume 7 Page 3026)

Set ¼ sec. post, from which
A B.Oak 12" dia. bears N.11½°W., 351 lks. dist.
A B.Oak 12" dia. bears S.69°W., 532 lks. dist.

Milo E. Godfrey, Deputy Co. Surveyor - V. Tracy; M.Stone
May-June 1963 - C.S. File 53/9-119

Found - Mound of rock at corner. (No record) (2/11/1918 Frear notes: "Germond ¼ cor. S.S." in Field Book 43 Pg. 55) (Info. added 10/91, V.L.& date added 5/12/2011 JC)
Old Oak, down & partly rotted, N.11½°W., 231.7 ft. opened & found fragmentary but legible reverse scribing "¼S".
30" B.Oak S.69°W., 351.1 ft. alive & standing, shows good scars, did not open.
Set brass cap at cor. mkd: County Surveyors Office, 1963 T24S R4W ¼ S31 / T25S R4W S 6
Replace rocks around cap.
New BTs - 15" W.Oak N.10½°W., 148.5 ft. mkd: ¼ S31 CS BT.
9" W.Oak S.28°E., 59.6 ft. mkd: ¼ S 6 C S BT.
Corner lies 8 feet west of a North & South fence line.

Fd. Ok by W.Barnes, July 1976 - M 60-70

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/10/2002 - C.S. File 66/32-4

Found - 1963 DCSO Brass Cap/iron pipe protrudes 12" above ground, mound of stone around base of BC/IP. Corner lies 8 ft. West of a N-S fence line.
12" B.Oak now badly rotted remains, found at rec. N.11½°W., 231.7 ft. (OBT)
12" now 34" dia., down & rotting B.Oak fd. at rec. S.69°W., 351.1 ft. (OBT)
15" now 24" dia., W.Oak with a fully healed double blaze bears N.10½°W., 148.5 ft. (1963)
9" now double trunked W.Oak with a fully healed double blaze on 16" dia., Westerly trunk, bears S.28°E., 59.6 ft. (1963)
New - 7" dia., D.Fir double blazed & scribed "¼ S6 CS BT" bears S.37½°W., 89.5 ft.
6" dia., D.Fir double blazed & scribed "¼ S6 CS BT" bears S.67½°E., 80.9 ft. - Compass decl. 17½°E.