TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. H. Byars, Contract #152 dated June 1871
(DCSO records, Volume 9 Page 3758)

Set ¼ sec. post, from which
A Fir 8" dia. bears East, 5 lks. dist.
A Fir 6" dia. bears S.45°W., 6 lks. dist.

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin and Roseberry - Special Instructions dated July 8, 1957 and July 15, 1958 - (DCSO records, Volume 29 Page 12308)

Point for corner determined at proportionate distance; there is no remaining evidence of ther original corner.
Set an iron post, 28" long 2½" dia. 26" in the ground, with brass cap marked: T25S R4W

¼
S 30|S 29
1957

from which
A Fir 10" dia. bears S.27½°E., 35 lks. dist. marked ¼ S29 BT.
A Fir 8" dia. bears N.27¼°W., 7 lks. dist. marked ¼ S30 BT.

Corner found OK - BLM Dependent Resurvey, Jelley and Rogers, Jan/June 1982 - (DCSO records, Vol. 45 Page 17521)