TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. H. Byars, Contract #152 dated June, 1871 (DCSO records, Volume 9 page 3755)

Set ¼ sec. post, from which
A Fir 8" dia. bears N.39°E., 32 lks. dist.
A Fir 8" dia. bears S.19°W., 14 lks. dist.

Wilford N. Haines, For: Mt. Baldy Lumber Company
February 15, 1956 - M 2-41

Set 36" angle iron with brass cap inscribed, Survey Point - Wilford N. Haines # 239, from the old BT in section 19. Scribed 30" Fir, S.75°26'E., 42.0 ft.

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin and Roseberry - Special Instructions dated July 8, 1957 and July 15, 1958 (DCSO records, Volume 29 page 12312-13)

The ¼ sec. cor. perpetuated with an angle iron, 36x1x1", firmly set 30" in the ground, with brass cap marked "Wilford N. Haines, @239 Survey Point, Drain, Ore.", from which
Orig. BT, A Fir 31" dia. bears S.19°W., 14 lks. dist. scribe marks ¼ visible on partly opened blaze.
A Fir 25" dia. bears S.70°E., 62 lks. dist. with scribe marks ¼ visible on scarred blaze.
At the corner point, set an iron post, 28" long 2½" dia. bears 24" in the ground, with brass cap mkd: T25S R4W ¼ S 19|S 20 1957 from which
A Fir 15" dia. bears S.30°E., 40 lks. dist., marked ¼ S20 BT.
A Fir 32" dia. bears S.34°W., 32 lks. dist. marked ¼ S19 BT.
Reset the angle iron alongside the iron post.
Cor. falls at the edge of logged area, bears N. & E.

Corner found and used - BLM Resurvey, 1983 - Jelley and Rogers - (DCSO records, Volume 45 page 17526)

Fd. OK - Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - Aug. 1997 - C.S. File 64/79-9