TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 200360

PRIMARY CORNER DESCRIPTION North 1/16 Cor Secs. 19 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin and Roseberry - Special Instructions dated July, 1957 and July 1958 - (DCSO records, Volume 29 Page 12313)

Point for N 1/16 sec. cor. of secs. 19 and 20.
Set an iron post, 28" long, 2½" dia. 24" in the ground, with brass cap marked: N 1/16
S 19|S 20
1957 from which
A Fir 13" dia. bears S.64½°E., 163 lks. dist. marked N 1/16 S20 BT.
A Fir 40" dia. bears N.30¼°W., 94 lks. dist. marked N 1/16 S19 BT.

Doug. Co. Surveyors Office - V. Tracy; J. Barnett; M. Darby Jan/Feb. 1965 - C.S. File 53/47-2

Found - 1957 BLM Brass cap.
40" now 42" Fir N.30¼°W., 62.0 ft., scribe visible on partially healed over face.
Other BT gone.
New BT - 4" D.Fir S.72°E., 12.5 ft. mkd: N 1/16 S20 CS BT.
This cor. lies on steep E. slope approx. 50 ft. W. of ravine.

Bureau of Land Management Dependent Resurvey - Group #1084 Jelley and Rogers - Survey, Jan/June 1982 - (DCSO records, Volume 45 Page 17526)

Found - 1957 Cadastral brass cap.
A sawed Fir stump 48" dia. bears N.30¼°W., 94 lks. dist. with healed blaze. (1957 BT)
A Fir 6" dia. bears S.72°E., 19 lks. dist. with healed double blaze. (Co. 1965 BT)
New BT - A Fir 6" dia. bears S.59½°W., 48 lks. dist. mkd. N 1/16 S19 BT.